New York State Department of Transportation PIA Safety Flag NB23U4W010

By: Malav Shah

Flag Date: April 20, 2023

Superseding Information:

No Flags Superseded

Structure Information

BIN: 1065318 Region: 11 - NEW YORK CITY

Feature Carried: 278I278IX2M23027 County: KINGS

Feature Crossed: 6TH AVENUE Political Unit: City of NEW YORK
Orientation: 8 - NORTHWEST Approximate Year Built: 1962

Posted Load Matches Inventory: Yes

Bridge Load Posting (Tons): Not Posted for Load

Primary Owner: New York State Department of Transportation

Primary Maintenance Responsibility: 12 - State - Subcontracted to another Party

Typical or Main Span Type: 3 - Steel, 02 - Stringer/Multi-Beam or Girder

This Bridge is not a Ramp Number of Spans: 322

Verbal Notification Information

Person Notified: Heinz Joachim, P.E. Date: April 20, 2023 1:20:00 PM

Of: NYSDOT Region 11

Signature Information

Signature: Malay Shah, P.E. 106620-1 Date: April 24, 2023

Reviewed By: Robert Kemp Date: April 24, 2023

Attachments: 5

Flag Date: April 20, 2023

Flagged Elements

No Flagged Elements

Flagged Condition Description


Location: Span 118, Pier 117, Column C1 end face (48th Street and 3rd Avenue intersection).

Description:

The junction box for the traffic light and attached to Column C1 is broken with exposed electric wires. This location is located at 3' above the ground on the sidewalk and can be accessed by walking. The area is temporarily secured with cones and caution tape.

Flag Date: April 20, 2023

Flag Photographs



Attachment Description: Safety PIA Flag Location

Photo Number:

Photo Filename: P4202468.JPG

BIN 1065318 Flag Date: April 20, 2023



Attachment Description: General view of the flagged condition under Span 118, column C1 at Pier 117. Looking Begin.

BIN 1065318

Flag Date: April 20, 2023

Photo Number: 3 Photo Filename: **P4202469.JPG**



Attachment Description: The sidewalk at the end face of Column C1 of Pier 117 under Span 118. The electrical junction box is broken with exposed wires. The area has been coned off with yellow caution tape. Looking Begin.

Photo Number:

BIN 1065318

Photo Filename: P4202472.JPG

Flag Date: April 20, 2023



Attachment Description: The sidewalk at the end face of Column C1 of Pier 117 under Span 118. The electrical junction box is broken with exposed wires. The area has been coned off with yellow caution tape. Looking Begin-

PIA Safety Flag NB23U4W010

BIN 1065318

Flag Date: April 20, 2023

Photo Number: 5 Photo Filename: P4202479.JPG



Attachment Description: The sidewalk at the end face of Column C1 of Pier 117 under Span 118. The electrical junction box is broken with exposed wires. The area has been coned off with yellow caution tape. Looking Begin-Right.